2-axis High Speed Interpolation/Normal Motion Controller Features

- Independent 2-axis controlling with high operating speed of max. 4Mpps
- Linear/Circular interpolation control (PMC-2HSP)
- Realizing a wide variety of operation up to 200 steps using 17 control commands combination (13 commands except arc/linear interpolation command for PMC-2HSN series)
- Various control interface available (USB, RS232C, RS485, Parallel I/F)
- Controlling up to 32 axes (16-unit) via RS485 serial communication (Modbus RTU)
- 4 operation modes: Jog, Continuous, Index, Program mode
- Symmetrical/asymmetrical trapezoid, S-shaped de/acceleration driving function

· ,	1	,
ase read "Safety Conside		
the instruction manual be	fore using.	

User Manual

Ple in t

- Please refer to user manual for detailed instructions and specifications.
- Visit our website (www.autonics.com) to download user manual and software [atMotion].
- User manual describes installing software, setting parameter and program, operation mode, and multi-axis operation, etc. to operate motion controller.

(except for PMC-2HSD-485)

Software (atMotion)

atMotion is the windows software designed to operate motion control for motion device.

PMC-2HS USB

- Compatible with Microsoft Windows 98, NT, XP (32-bit, 64-bit), Vista (32-bit, 64-bit), 7 (32-bit, 64-bit), 8 (32-bit, 64-bit) and 10 (32-bit, 64-bit)
- Supports 1200, 2400, 4800, 9600, 19200, 38400, 57600, 115200 bps communication speeds
- Available to use on all OS supported COM ports (COM1 to COM256)
- Multilingual support (Korean, English)
- Provides the calculator for convenience (calculates PPS center of interpolation end coordinates)

MC -	2HSP – U	ISB	(calculates PPS, center of interpolation, end coc
		Communication type	USB	USB / RS232C
			485	RS485 / RS232C
	Axis/Type		2HSP	2-axis high speed interpolation
			2HSN	2-axis high speed normal
Item			- PMC	Programmable Motion Controller

Specifications

Model		PMC-2HSP-USB	PMC-2HSP-485	PMC-2HSN-USB	PMC-2HSN-485	
Control a	ixes	2-axis	·	·	·	
Motor for control Pulse train input stepper motor or servo motor						
Power supply		24VDC==				
Allowable voltage range 90 to 110% of rated voltage						
Power consumption		Max. 6W				
In-Positic	on range	-8,388,608 to 8,388,60)7 (selectable absolute/rel	ative value, available pulse-	scaling function)	
Drive spe	eed	1pps to 4Mpps (1 to 8	,000pps×magnification 1 to	o 500)		
Pulse ou	tput method	1-Pulse/2-Pulse outpu	t method (line driver outpu	it)		
Operatio	n mode	Jog / Continuous / Ind	ex / Program mode			
Number (of index steps	64 indexes per axis		÷		
	Steps	200-step				
Program Control command ABS, INC, HOM, LID ^{×1} , CID ^{×1} , FID ^{×1} , RID		¹ , CID ^{*1} , FID ^{*1} , RID ^{*1} , TII	M, JMP, REP, RPE, ICJ, IRE	D, OPC, OPT, NOP, END		
function	Start	Available power On pr	ogram auto start setting			
	Home search	Available power On home search setting				
Home search mode High speed near home search (Step 1) \rightarrow Low speed near home search (Step 2) \rightarrow Encoder Z phase search (Step 3) \rightarrow Offset movement (Step 4)				tep 2) \rightarrow		
I/O		Parallel I/F (CN3): 13 X-axis (CN4) / Y-axis		s (general-purpose I/O, two	of each)	
Environ	Ambient temperature	0 to 45°C, storage: -15	5 to 70°C			
-ment	Ambient humidity	20 to 90%RH, storage: 20 to 90%RH				
Accessor	ry			PI/F, X-axis, Y-axis), RS2320 [RS485 type] RS485 conne	communication cable (1.5m): 1 ector: 1	
Approval		CE 🕼	CE	CE 🕼	CE	
Weight ^{*2}		Approx. 344g (approx. 101.5g)	Approx. 308.7g (approx. 101.6g)	Approx. 344g (approx. 101.5g)	Approx. 308.7g (approx. 101.6g)	

Environment resistance is rated at no freezing of condensation

Ordering Information





PMC-2HS -485

2-axis High Speed Interpolation/Normal Motion Controller

Standard Operation Method

There are three methods to operate the motion controller.


- Operation by PC
- Connect a PC and the controller with communication cable and run dedicated program (atMotion). • Operation by Parallel I/F
- Connect a sequence controller or switch to Parallel I/F.
- Operation by serial communication (dedicated communication protocol)


Using serial communication protocol, operate according to program writing by user.

Program Com	mands		
Command type	Code	Description	
	ABS	Move absolute position	
	INC	Move relative position	
	НОМ	Home search	
Drive commands	LID ^{*1}	2-axis linear interpolation	
	CID ^{×1}	2-axis CW circular interpolation	
	FID ^{*1}	2-axis CW arc interpolation	
	RID ^{*1}	2-axis CCW arc interpolation	
	ICJ	Jump input condition	
1/O commondo	IRD	Stand-by external input	
I/O commands	OPC	ON/OFF output port	
	OPT	ON pulse from output port	
	JMP	Jump	
Program control commands	REP	Start repetition	
	RPE	End repetition	
	END	End program	
Others	TIM	Timer	
Oulers	NOP	No operation	


※1: These commands are only for PMC-2HSP series

Unit Descriptions





External I/O Terminal Connection



1. Power / Status indicator

Used to indicate power, communication status of the controller, and operation status of each axis.

- 2. Power connector terminal
 - Used to connect power for controller

Connector

- 3. RS232C connector terminal Used to connect RS232 serial (RJ12-DSUB9) connection cable
- 4. USB/RS485 connector terminal Used to connect USB and RS485 connection cable
- 5. External I/O connector terminal Used to operate various drives through input and output of Parallel I/F, X, Y
- 6. ID select switch Used to set unique ID for each node in case of RS485 communication

	51
Connector no.	Description
CN1	Power connector
CN2	RS232C connector
CN3	Parallel I/F connector
CN4	X-axis I/O connector
CN5	Y-axis I/O connector
CN6	PMC-2HSP/2HSN-USB: USB connector
CINO	PMC-2HSP/2HSN-485: RS485 connector
IDS	ID selection switch



SENSORS

CONTROLLERS

MOTION DEVICES


Power Connector (CN1)

Pin no.	Signal name
1	24VDC
2	GND (0V)

RS232C Connector (CN2)

Pin no.	Signal name	I/O	Description
1	TXD	Output	Receiving data
2	RXD	Input	Transmitting data
3	GND	—	Ground
4	—	—	
5	—	—	N·C
6	—	—	

% The internal connection diagram of RS232C communication cable is shown as below.




Parallel I/F Connector (CN3)

The Parallel I/F connector which is connected with a sequencer or mechanical contacts operates motion controller same as PC program. When input signal is ON, the input signal terminal and GEX terminal are connected by mechanical contacts or open collector output and open collector output transistor is ON when the output signal is ON.

	,		· · · · · · · · · · · · · · · · · · ·
Pin no.	Signal name	I/O	Description
1	RESET	Input	Reset
2	HOME	Input	Home search start command
3	STROBE	Input	Drive start command
4	X/JOG Y+	Input	X-axis designate/Jog Y+
5	Y/JOG Y-	Input	Y-axis designate/Jog Y-
6	STEPSL0/RUN+/JOG X+	Input	Register designate 0/Run+/Jog X+
7	STEPSL1/RUN-/JOG X-	Input	Register designate 1/Run-/Jog X-
8	STEPSL2/SPD0	Input	Register designate 2/Drive speed designate 0
9	STEPSL3/SPD1	Input	Register designate 3/Drive speed designate 1
10	STEPSL4/JOG	Input	Register designate 4/Jog designate
11	STEPSL5/STOP	Input	Register designate 5/Drive stop
12	MODE0	Input	Operation mode designate 0
13	MODE1	Input	Operation mode designate 1
14	X DRIVE/END	Output	X-axis drive/Drive end pulse
15	Y DRIVE/END	Output	Y-axis drive/Drive end pulse
16	X ERROR	Output	X-axis error
17	Y ERROR	Output	Y-axis error
18	GEX	—	Ground
19	GEX		Ground
20	VEX	—	Power supply for sensor (24VDC, max. 100mA)






• X, Y-axis Input/Output Connector (CN4, CN5)

CN4 and CN5 are I/O signals for X-axis and Y-axis respectively. The pin arrangement of CN4 and CN5 are equal. 'n' in the table means X for CN4 and Y for CN5.

Pin no.	Signal name	I/O	Description
1	n P+P	Output	Drive pulse in the CW + direction
2	n P+N	Output	Drive pulse in the CW - direction
3	n P-P	Output	Drive pulse in the CCW + direction
4	n P-N	Output	Drive pulse in the CCW - direction
5	n OUT0	Output	General output 0
6	n OUT1	Output	General output 1
7	n IN0	Input	General input 0
8	n IN1	Input	General input 1
9	n STOP2	Input	Encoder Z-phase
10	n STOP1	Input	Home
11	n STOP0	Input	Near Home
12	n LMT+	Input	+ direction limit
13	n LMT-	Input	- direction limit
14	EMG	Input	Emergency stop
15	GEX	—	Ground
16	VEX	—	Power supply for sensor (24VDC, max. 100mA)



о G о А о в

(Y) Closed Loop Stepper Systen

SENSORS

CONTROLLERS

MOTION DEVICES

SOFTWARE

(Z) Stepper Motors

(AA) Drivers

AB) Notion

%CN4, 5 input/output is same as CN3 input/output connections.


Drive pulse output of motion controller which is inputted to motor driver is line driver output.

RS485 Connector (CN6)

Pin no.	Signal name	I/O	Description
1	В (-)	I/O	Transmitting / Receiving data
2	A (+)	I/O	Transmitting / Receiving data
3	G	—	×1

X1: Connect the ground when it is required depending on communication environments.


Connections




< Basic configuration of the motion controller (configuration only for X-axis) >

I/O Connections Diagram


◎ Input/Output connection circuit (CN3)



Section 2 Constant Constant



© Example of limit and home sensor connection



Dimensions

(unit: mm)

